



**Cilindrična kliza čaura  
– tip PCM**



**Klizna čaura sa flanšom  
– tip PCMF**



SKF klizne čaure imaju klizni sloj od PTFE kompozitnog materijala (od teflona) i ne zahtevaju dodatno podmazivanje.



|              |
|--------------|
| PCM 3x4.5x3  |
| PCM 4x5.5x6  |
| PCM 4x5.5x10 |
| PCM 5x7x5    |
| PCM 5x7x8    |
| PCM 5x7x10   |
| PCM 6x8x6    |
| PCM 6x8x8    |
| PCM 6x8x10   |
| PCM 8x10x6   |
| PCM 8x10x8   |
| PCM 8x10x10  |
| PCM 8x10x12  |
| PCM 10x12x8  |
| PCM 10x12x10 |
| PCM 10x12x12 |
| PCM 10x12x15 |
| PCM 10x12x20 |
| PCM 12x14x8  |
| PCM 12x14x10 |
| PCM 12x14x12 |
| PCM 12x14x15 |
| PCM 12x14x20 |
| PCM 12x14x25 |
| PCM 13x15x20 |
| PCM 14x16x10 |
| PCM 14x16x12 |
| PCM 14x16x15 |
| PCM 14x16x20 |
| PCM 15x17x10 |
| PCM 15x17x12 |
| PCM 15x17x15 |
| PCM 15x17x20 |
| PCM 16x18x10 |
| PCM 16x18x12 |
| PCM 16x18x15 |

|              |
|--------------|
| PCM 16x18x20 |
| PCM 16x18x25 |
| PCM 17x19x20 |
| PCM 18x20x15 |
| PCM 18x20x20 |
| PCM 18x20x25 |
| PCM 20x22x10 |
| PCM 20x22x20 |
| PCM 20x23x10 |
| PCM 20x23x15 |
| PCM 20x23x20 |
| PCM 20x23x25 |
| PCM 20x23x30 |
| PCM 22x25x15 |
| PCM 22x25x20 |
| PCM 22x25x25 |
| PCM 24x27x15 |
| PCM 24x27x20 |
| PCM 24x27x30 |
| PCM 25x28x12 |
| PCM 25x28x15 |
| PCM 25x28x20 |
| PCM 25x28x25 |
| PCM 25x28x30 |
| PCM 25x28x40 |
| PCM 25x28x50 |
| PCM 28x32x20 |
| PCM 28x32x25 |
| PCM 28x32x30 |
| PCM 30x34x15 |
| PCM 30x34x20 |
| PCM 30x34x25 |
| PCM 30x34x30 |
| PCM 30x34x40 |
| PCM 32x36x20 |
| PCM 32x36x30 |
| PCM 35x39x20 |
| PCM 35x39x30 |
| PCM 35x39x40 |

|               |
|---------------|
| PCM 35x39x50  |
| PCM 40x44x20  |
| PCM 40x44x30  |
| PCM 40x44x40  |
| PCM 40x44x50  |
| PCM 45x50x20  |
| PCM 45x50x30  |
| PCM 45x50x40  |
| PCM 45x50x50  |
| PCM 50x55x20  |
| PCM 50x55x30  |
| PCM 50x55x40  |
| PCM 50x55x60  |
| PCM 55x60x20  |
| PCM 55x60x25  |
| PCM 55x60x30  |
| PCM 55x60x40  |
| PCM 55x60x50  |
| PCM 55x60x60  |
| PCM 60x65x15  |
| PCM 60x65x30  |
| PCM 60x65x40  |
| PCM 60x65x60  |
| PCM 60x65x70  |
| PCM 65x70x30  |
| PCM 65x70x50  |
| PCM 65x70x70  |
| PCM 70x75x40  |
| PCM 70x75x50  |
| PCM 70x75x70  |
| PCM 75x80x50  |
| PCM 75x80x60  |
| PCM 75x80x80  |
| PCM 80x85x40  |
| PCM 80x85x60  |
| PCM 80x85x100 |
| PCM 85x90x30  |
| PCM 85x90x60  |
| PCM 85x90x100 |



|                 |
|-----------------|
| PCMF 6x8x4      |
| PCMF 6x8x8      |
| PCMF 8x10x5.5   |
| PCMF 8x10x7.5   |
| PCMF 8x10x9.5   |
| PCMF 10x12x7    |
| PCMF 10x12x9    |
| PCMF 10x12x12   |
| PCMF 10x12x17   |
| PCMF 12x14x7    |
| PCMF 12x14x9    |
| PCMF 12x14x12   |
| PCMF 12x14x15   |
| PCMF 12x14x17   |
| PCMF 14x16x12   |
| PCMF 14x16x17   |
| PCMF 15x17x9    |
| PCMF 15x17x12   |
| PCMF 15x17x17   |
| PCMF 16x18x12   |
| PCMF 16x18x17   |
| PCMF 18x20x12   |
| PCMF 18x20x17   |
| PCMF 18x20x22   |
| PCMF 20x23x11.5 |
| PCMF 20x23x15   |
| PCMF 20x23x16.5 |
| PCMF 20x23x21.5 |
| PCMF 25x28x11.5 |
| PCMF 25x28x16.5 |
| PCMF 25x28x21.5 |
| PCMF 30x34x16   |
| PCMF 30x34x26   |
| PCMF 35x39x16   |
| PCMF 35x39x26   |